

Tech Bulletin: C2R-FRD1 Factory Amplified System Shutting Down / Resetting

PROBLEM: In some cases, Ford amplified systems may cause feedback to the C2R-FRD1 module and cause the radio to turn off intermittently or restart especially at higher volumes.

FIX: Cut the White/Green wire coming from the C2R-FRD1 module and solder a 1 amp diode (Radio Shack part no. 1N4005) or equivalent, inline on the white/green wire as shown in the diagram below. Make sure that the diode's stripe is towards the harness of of the C2R module.

